

EOL – 110616	MERCURY ELECTRONICS www.mercury-crystal.com	Revision: 0
Product: (V)M38		Page 1 of 2
Model: (V)M38		Date: June 16, 2011

Product End of Life Notice.
EOL No. 110616


As part of our on-going product lifecycle management process, Mercury decided to discontinue VM38 and M38 VCTCXO and TCXO products. This decision was based on the fact that (V)M38 and (V)M39 are simply different in metal can height. With the continued production and product support of (V)M39 products, current (V)M38 customers should see no impact to their applications.

Affected Products:

- ◆ VM38: Voltage controlled temperature compensated oscillators in VM38 package
- ◆ M38: Temperature compensated oscillators in M38 package

Reasons for the change:

- ◆ On-going product lifecycle management process
- ◆ Simply product varieties
- ◆ (V)M38 and (V)M39 are different only in package height



EOL – 110616	MERCURY ELECTRONICS www.mercury-crystal.com	Revision: 0
Product: (V)M38		Page 2 of 2
Model: (V)M38		Date: June 16, 2011

Impact to customers: None.

- ◆ Pin spacing is identical to both (V)M38 and (V)M39
- ◆ Pin electrical connections are identical to both (V)M38 and (V)M39

Last time buy: July 31, 2011

◆ Unless special arrangement is made, (V)M38 orders received after July 31, 2011 will automatically be converted to (V)M39 with a written notice from Mercury sales department.

Implementation Plan:

- ◆ Last time buy of (V)M38 is July 31, 2011
- ◆ Unless special arrangement is made, (V)M38 orders received after July 31, 2011 will automatically be converted to (V)M39 with a written notice from Mercury sales department.

Suggestions to customers:

- ◆ Please contact Mercury if this change requires re-qualification.
- ◆ Change part number from VM38 to VM39 and/or M38 to M39 for the product prefix.

If any concern: Please email your concern to sales-tw@mercury-crystal.com (Asia and Europe) or sales-us@mercury-crystal.com (N. and S. Americas)

